



Populate P5 with a 2 pin connector  
Header retains option to use a 4 pin  
by cutting solder jumpers and using a different header.




2 or 4 wire PT100 support  
Along with Thermistors



Mounting holes



2.9mm holes for the arm ends



Ziptie for strain relief

CERN OHL 1.2	
Duet3D	
Sheet: /	
File: SmartEffector.sch	
<b>Title: SmartEffector</b>	
Size: A4	Date: 2019-06-02
KiCad E.D.A. kicad (5.0.0)	Rev: V2.0
	Id: 1/1